
































# TMQ C-Plot Shortcut Keys

Function	Description	C-Panel	Keyboard	Mouse
Cancel	Used to end an operation or function without executing this operation			
OK	This key is used to verify operations			
Zoom In	Increases the size of the chart, less of the chart is visible on the screen			
Zoom Out	Decreases the size of the chart, more of the chart is visible on the screen			
Center Vessel	Modifies the display so that the vessel is in the center of the screen			
Go To Cursor (On/Off)	Creates a quick route between the vessel's current position and the cursor.			
Main Menu	Displays the Main Menu			
Object Information	Displays Information for the selected Object			
Chart Information	Displays information for the currently loaded chart			
Remove Object	Removes a selected object (Mark, Event, Track, etc)			Various: Object Dependant



# TMQ C-Plot Shortcut Keys

Function	Description	C-Panel	Keyboard	Mouse
Track	This will toggle the track on and off			
Add Event	Places an Event symbol at the vessel's current position			
Add Mark	Places a Mark at the current cursor position			
Edit Object	Enables editing of the object at the position of the cursor			Various: Object Dependant
Load Chart	Load a new chart			
Load Best HCRF Chart	Loads the most suitable HCRF chart for the current cursor position			
Change Palette	Changes the current palette			
Screen Shift	Moves the chart in 1/3 of the screen in the desired direction			
Exit	Close C-Plot and return to Windows			